# PHIL TECHNOLOGIES PRIVATE LIMITED

**Release Notes For
MIS100V2 RD Service - Windows
Version 1.0.5**

07-Feb-2024

Table of Contents

1. Introduction

MIS100V2 RD Service facility to capture biometric data of user/resident that will be used Authentication/EKYC using Aadhaar authentication/EKYC API.

2. About This Release

Features added in this release as below.

Based on UIDAI circular with subject "Delta certification for inclusion of additional information in device information parameters", below two parameters added in additional_info.

```
<additional_info>
        <Param name="modality_type" value="Iris" />
        <Param name="device_type" value="L0" />
</additional_info>
```

3. Compatible Products

This product has been tested on the following platforms and below MIS100V2 Driver Setup.

Platform Supports

1) Windows 7 (64 bit & 32 bit)
2) Windows 8 (64 bit & 32 bit)
3) Windows 10 (64 bit & 32 bit)

Prerequisites

1) MIS100V2 Driver Setup 2.1.0.0 or higher
Note: MIS100V2 Driver setup will install below setups as prerequisites.

A) VC++ 2008 Redist (64 bit & 32 bit)

B) VC++ 2013 Redist (32 bit)
C) VC++ 2015 Redist (32 bit)
D) Dot Net Framework 4.5.2 or higher
(Note: It will be required for Windows 7 only. for Windows 8 or higher, Dot Net Framework 4.5.2 or higher version will be included with OS. You may only require enabling features if not available)

4. Upgrades

There are two processes to upgrade MIS100V2 RD Service Version 1.0.4 to 1.0.5.

1) Manual Upgrade Process

You can download MIS100V2 RD service setup version 1.0.5 from below download Portal.
 https://www.radiumbox.com/download

> **Product Category -** Authentication Devices – Aadhaar
>
> **Products –** MIS100V2
>
> **RD Service –** MIS100V2 Windows RD Service

2) Auto upgrade process from Management Server

> Management Server will have facility to upgrade MIS100V2 RD Service 1.0.4 to 1.0.5 remotely over the air.
> On every restart, RD Service will check latest version available on Management Server, and Management Server will provide upgraded packages to RD Service.

5. New Features

> NA

6. Known Bugs and Limitations

6.1 General Note

> MIS100V2 RD service setup version 1.0.5 having dependency of Dot Net Framework 4.5.2 or higher and VC++ redist 2013 & 2015, so its recommendation to Install MIS100V2 Driver Setup 2.1.0.0 or higher.
> If Dot Net Framework 4.5.2 or higher and VC++ redist 2013 & 2015 already available in system then there is no need to upgrade MIS100V2 Driver Setup.

6.2 Defect or Bug

> NA