

# PHIL TECHNOLOGIES PRIVATE LIMITED



# Radium



**For MFS100  
RD Service - Android  
Release Notes  
Version 1.0.9  
22-May-2023**



	<b>PHIL TECHNOLOGIES PRIVATE LIMITED</b>	
	Product Release Notes (MFS100 RD Service - Android)	22.05.2023

## Table of Contents

<b>Table of Contents</b>	1
<b>1. Introduction</b>	2
<b>2. About This Release</b>	2
<b>3. Compatible Products</b>	2
<b>4. Upgrades</b>	2
<b>5. New eatures</b>	3
<b>6.Known Bugs and Limitations</b>	3
6.1 General Note	3
6.2 Defect or Bug	3

	<b>PHIL TECHNOLOGIES PRIVATE LIMITED</b>	
	Product Release Notes (MFS100 RD Service - Android)	22.05.2023

## 1. Introduction

MFS100 RD Service facility to capture biometric data of user/resident that will be used for Authentication/EKYC using Aadhaar authentication/EKYC API.

## 2. About This Release

Features added in this release as below.

- ☒ Migrate safety net AP Ito play integrity API for check device root status.
- ☒ App security improvements.
- ☒ Bug fixing for browser support.

## 3. Compatible Products

This product has been tested on the following platforms.

### Platform Supports

- ☒ Android5.0 and above all OS

### Prerequisites

- ☒ USB host enable handsets
- ☒ GMS certified handsets(Non Rooted OS)

## 4. Upgrades

Follow below process to upgrade MFS100 RD Service Version 1.0.8 to 1.0.9.

- 1) Open Play Store
- 2) Search “**Mantra RDService**”
- 3) Select “**Mantra RDService**” from search list

	<b>PHIL TECHNOLOGIES PRIVATE LIMITED</b>	
	Product Release Notes (MFS100 RD Service - Android)	22.05.2023

- 4) Click on “**Update**” to upgrade RDService

## 5. **New Features**

NA

## 6. **Known Bugs and Limitations**

### 6.1 **General Note**

The RDService works with only GMS certified device, it requires to pass google play integrity test google play integrity test may require latest play store update and play service update in android device.

### 6.2 **Defect or Bug**

NA